

Technical Newsletter

#tn12022-0001e
1 / 1



Notice Regarding Installation of Maintenance Switch Alternative Part





Applicable models

DFD6360A, DFD6361, DFD6361 half cut specification, DFD6361 EAD specification, DFD6362

Notice

Due to the impact of the global parts supply shortage, we have decided to install alternative maintenance switches on some dicing saws.

There is no major difference in the maintenance switch's shape between the alternative part and the existing part, but the key's shape is different. If you have both keys, verify which is the right one by actually inserting them.

		Existing part	Alternative part
Maintenance switch	Appearance		
	Part no.	EKFM-910002-0	EKFM-010082-0
Keys	Appearance		
	Part no.	DSZA165KK01-0	DSZAR6C6600-0

As of December 2021, we are shipping machines equipped with the alternative maintenance switch and machines equipped with the existing maintenance switch concurrently.

The operation does not change regardless of which maintenance switch it is.

Inquiries

For inquiries regarding this matter, please contact a DISCO sales representative or customer engineer.