

Technical Newsletter

#tnl2018-0012e
1 / 2



6000/600 Series: Caution regarding the Use of the UV Lamp

Introduction


If you use any UV lamp other than DISCO genuine products (hereinafter referred to as "non-genuine product"), trouble unexpected by DISCO may occur.

Applicable model

Series	Applicable model
6000 series	DFD6240/DFD6340/DFD6341/DFD6450/DFD6240 RR Specification
600 series	DFD640/DFD641/DFD650/DFD651/DFD680/DFD681 DFD690/DFD691

Difference between the genuine and non-genuine products

Due to production stoppage of the UV lamp that has been in use on the DISCO machines, we sell our original lamps with DISCO logo as genuine products, as a substitute. A lamp maker sells other substitute for that, but we have determined that it is not substitutable because the illuminance is insufficient.

	Genuine product		Non-genuine product
	Discontinued part	DISCO's substitute	The lamp maker's substitute*
Appearance	   Purple	   White, with DISCO logo	   Purple
Maker model No.	6W : FL6BLB 4W : FL4BLB	6W : FL6BL 4W : FL4BL	6W : FL6BLB/N 4W : FL4BLB/N
Part No.	6W : DE AFL6BLB01-0 4W : DE AFL4BLB01-0	6W : DE AFL6BL-02-0 4W : DE AFL4BL-02-0	Unregistered

*This is a non-genuine product. Compared to the genuine product, the illuminance is insufficient by approximately 20%.

If you use the non-genuine product on a DISCO machine, you may be unable to obtain the same process results as with the genuine product.

Technical Newsletter

#tnl2018-0012e
2 / 2



Handling problems caused by non-genuine products

- Payment of investigation expenses required in order to identify the cause of the defect or failure may be requested, and the warranty period may be considered no longer valid.
- The problem occurs within the warranty period, a fee will be charged for handling defects, failures, etc., that occur when using non-genuine products.

Inquiries

Please contact your local DISCO sales representative or DISCO customer engineer if you have any questions regarding this matter.
